

	Type	Hits	Search Text
1	IS&R	2	("20020139173").PN.
2	IS&R	2	("6604407").PN.
3	BRS	2	("6604407").URPN.
4	IS&R	6824	((701/29) or (73/49.7,40,40.5r) or (123/518,519,520) or (702/51)).CCLS.
5	BRS	2	S1 and leak
6	BRS	2127	S4 and leak
7	BRS	612	S4 and leak and vehicle
8	BRS	549	S4 and leak and vehicle and (fuel or gas or gasoline or petrol)
9	IS&R	2	("5845265").PN.
10	BRS	9	("20020062861"   "5295472"   "5396873"   "5443051"   "5911209"   "6276344"   "6321727"   "6382192"   "6470862").PN.
11	IS&R	6824	((701/29) or (73/49.7,40,40.5r) or (123/518,519,520) or (702/51)).CCLS.
12	BRS	549	S11 and leak and vehicle and (fuel or gas or gasoline or petrol)
13	BRS	205	S12 and ((engine or ignition) with off)
14	BRS	1800	leak with tank with pressure
15	BRS	443	(leak with tank with pressure) and vehicle and engine
16	BRS	300	(leak with tank with pressure) and vehicle and engine and (negative or vacuum)
17	BRS	83	(leak with tank with negative with pressure) and vehicle and engine

	<b>DBs</b>
<b>1</b>	<b>US-PGPUB; USPAT; EPO; JPO; DERWENT</b>
<b>2</b>	<b>US-PGPUB; USPAT; EPO; JPO; DERWENT</b>
<b>3</b>	<b>USPAT</b>
<b>4</b>	<b>US-PGPUB; USPAT; EPO; JPO; DERWENT</b>
<b>5</b>	<b>US-PGPUB; USPAT; EPO; JPO; DERWENT</b>
<b>6</b>	<b>US-PGPUB; USPAT; EPO; JPO; DERWENT</b>
<b>7</b>	<b>US-PGPUB; USPAT; EPO; JPO; DERWENT</b>
<b>8</b>	<b>US-PGPUB; USPAT; EPO; JPO; DERWENT</b>
<b>9</b>	<b>US-PGPUB; USPAT; EPO; JPO; DERWENT</b>
<b>10</b>	<b>US-PGPUB; USPAT; USOCR</b>
<b>11</b>	<b>US-PGPUB; USPAT; EPO; JPO; DERWENT</b>
<b>12</b>	<b>US-PGPUB; USPAT; EPO; JPO; DERWENT</b>
<b>13</b>	<b>US-PGPUB; USPAT; USOCR</b>
<b>14</b>	<b>US-PGPUB; USPAT; EPO; JPO; DERWENT</b>
<b>15</b>	<b>US-PGPUB; USPAT; EPO; JPO; DERWENT</b>
<b>16</b>	<b>US-PGPUB; USPAT; EPO; JPO; DERWENT</b>
<b>17</b>	<b>US-PGPUB; USPAT; EPO; JPO; DERWENT</b>

	Type	Hits	Search Text
18	BRS	162	(leak same tank same negative same pressure) and vehicle and engine
19	IS&R	1	("0666072").PN.
20	IS&R	2	("6666072").PN.
21	BRS	10	("20020062861"   "5295472"   "5396873"   "5443051"   "5911209"   "6276344"   "6321727"   "6382192"   "6470862").PN. OR ("6666072").URPN.
22	BRS	62	(leak same tank same negative same pressure) and vehicle and ((engine or ignition) with off)
23	IS&R	6940	((701/29) or (73/49.7,40,40.5r) or (123/518,519,520) or (702/51)).CCLS.
24	BRS	120	S23 and @pd>"20050316"

	<b>DBs</b>
<b>18</b>	<b>US-PGPUB; USPAT; EPO; JPO; DERWENT</b>
<b>19</b>	<b>US-PGPUB; USPAT; EPO; JPO; DERWENT</b>
<b>20</b>	<b>US-PGPUB; USPAT; EPO; JPO; DERWENT</b>
<b>21</b>	<b>US-PGPUB; USPAT; USOCR</b>
<b>22</b>	<b>US-PGPUB; USPAT; EPO; JPO; DERWENT</b>
<b>23</b>	<b>US-PGPUB; USPAT; EPO; JPO; DERWENT</b>
<b>24</b>	<b>US-PGPUB; USPAT; EPO; JPO; DERWENT</b>